

தமிழ்நாடு தீயணைப்பு மற்றும் மீட்புப்பணிகள் துறை

தடையின்மைச் சான்று

எழும்பூர் தீயணைப்பு-மீட்புப்பணிகள் நிலையம்.

ந.க.எண்: 382/VB/EGM/2020

நாள் :10.11.2020

எண் 53/2020

பொருள்: தீயணைப்பு-மீட்புப்பணிகள் துறை-எழும்பூர் தீயணைப்பு-
மீட்புப் பணிகள் நிலையம் - பள்ளிக்கூடம் நிறுவிடபள்ளிக்கூடத்திற்கு
அங்கீகாரம் வழங்கிடதடையின்மைச் சான்றுவழங்குதல் - குறித்து.

பார்வை: 1. அரசுஆணை எண்.122,பள்ளிகல்வி (2) துறை, நாள்.14.09.2004
2. அரசுஆணை எண்.123,பள்ளிகல்வி (2) துறை, நாள்.14.09.2004,
3. THE HEADMISTRESS,
என்பவரிடமிருந்து பெறப்பட்ட விண்ணப்பம், நாள் 10.10.2020

பார்வையில் காணும் அரசாணை மற்றும் விண்ணப்பத்தின்படி கதவு இலக்கம்
NO.43 (13A) VANNIER STREET, CHOLAIMEDU, CHENNAI-600
094 என்ற முகவரியில் நிறுவப்பட்டுள்ள M/S LALCHAND
MILAPACHAND DADHA SENIOR SECONDARY SCHOOL என்ற
பள்ளியினை 10.10.2020 அன்று எழும்பூர் நிலைய அலுவலர் திரு.அ. ஜேம்ஸ் அருள்
பிரகாஷ் என்பவரால் ஆய்வு செய்யப்பட்டது. இவ்விடத்தில் பள்ளிக்கூடத்திற்கு
அங்கீகாரம் வழங்கிட கீழ்க்காணும் நிபந்தனைகளுக்கு உட்பட்டு (10.11.2020 முதல்
09.11.2021வரை) தீயணைப்பு மற்றும் மீட்புப்பணிகள் நோக்கிலிருந்து யாதொரு தடையும்
இல்லை.

CONDITIONS

1. This License is valid for One year from the date of issue.
2. Fire Safety Systems should be maintained in good working condition.
3. Mock drill to be conducted periodically with the help of local fire brigade.
4. Any erection of permanent or temporary structure should be intimated to this department.
5. A trained Fire Service Person, preferably retired one should be appointed.
6. Further to limit the occupant load and to ensure better fire and life safety measures the following additional measures are insisted.
 - a) Building occupancy capacity should not be more than 4 people per Sq. meter as per the National Building Code-2005.
 - b) The staircase treads and flooring shall be treated with rough finish (grooving) to avoid falling of children.
 - c) As per Para 6.3 of the BIS Standards IS 14435:1997 as the classrooms have only one entrance, the capacity of the class rooms shall have to be limited to 45 students.

d) Periodical maintenance and care should be taken to maintain all fire protection equipments.

e) Mock drill has to be conducted at regular intervals in consultation with the District Officer, Fire and Rescue Services, Chennai City Central District at Kilpauk.

f) The classrooms should always be in the ground floor upto 3rd standards.

g) The classroom doors/ windows should be made of either non-combustible material or materials with high fire-resistance rating.

h) The classroom doors/ windows shall always open outwards.

i) The classroom doors/ windows shutters when opened should not obstruct movement along the exit or escape route.

j) A Class room shall have two entrances. One door with opening towards the teachers end and the other door on the other end of the class room with only a simple latch / tower bolt arrangement for locking from inside. This door shall not have any arrangement for locking from outside.

k) The school shall have proper Evacuation of Plan of action to rescue the children during any emergency in the school premises.

If here is any violation and deviation from the Govt. Rule and Act the License issued will stand cancelled.



11.11.2020
தலைவர்
தமிழ்நாடு அரசு
எழும்பூர், சென்னை-600 008.

பெறுநர்:

THE HEADMISTRESS,
M/S LALCHAND MILAPACHAND
DADHA SENIOR SECONDARY SCHOOL,
NO.43 (13A) VANNIER STREET,
CHOO LAIMEDU, CHENNAI-600 094.

நகல்: மாவட்ட அலுவலர், மத்திய சென்னை மாவட்டம்